



Copyright American Welding Society  
Provided by IHS under license with AWS  
No reproduction or networking permitted without license from IHS

# The Everyday Pocket Handbook for Arc Welding Steel



a series

Compiled as a useful tool  
for on-the-job welding  
personnel by an AWS  
**Presidential Task Group**

Licensee=Aramco HQ/9980755100  
Not for Resale, 01/08/2006 05:06:54 MST

Reproduced by Global Engineering  
Documents With the Permission of  
AWS Under Royalty Agreement



# American Welding Society

---

© 1994 by American Welding Society. All rights reserved.

Printed in the United States of America

**Note:** Although care was taken in choosing and presenting the data in this guide, AWS cannot guarantee that it is error free. Further, this guide is not intended to be an exhaustive treatment of the topic and therefore may not include all available information, including with respect to safety and health issues. By publishing this guide, AWS does not insure anyone using the information it contains against any liability or injury to property or persons arising from that use.

# Table of Contents

Basic Safety Precautions .....	4	Carbon Arc Gouging Electrodes .....	15
Electrodes: Classification, Size, Amps, Deposition Rate		Deposition Rate for Mild Steel for GMAW .....	16
Classification System for Carbon Steel		Recommended Copper Cable Sizes .....	17
Electrodes for SMAW .....	6	Guide to Electrode Conditioning and Storage .....	18
SMAW E6010 Electrodes .....	7	Welding Positions — Fillet (plate) .....	19
SMAW E6011 Electrodes .....	7	Welding Positions — Groove (plate) .....	20
SMAW E6012 Electrodes .....	8	Welding Positions — Pipe .....	21
SMAW E6013 Electrodes .....	8	Thickness and Weight of Steel Plates —	
SMAW E7018 Electrodes .....	9	1/32 to 2 inch .....	23
SMAW E7024 Electrodes .....	9	How to Use Weld Fillet Gage .....	25
Classification System for Solid and Composite		Pipe Size and Wall Thicknesses .....	26
Carbon Steel Electrodes for GMAW .....	10	Tests to Identify the Material .....	27
GMAW ER70S-X Short Arc Electrodes .....	11	Schedule for Oxyfuel Cutting	
GMAW ER70S-X Spray Arc Electrodes .....	11	using Natural Gas .....	29
GMAW E70C-XX Metal Cored Electrodes .....	12	using Acetylene Gas .....	30
Classification System for Carbon Steel		using Propylene Gas .....	31
Electrodes for FCAW .....	13	Basic Welding Symbols and Their Location .....	32
FCAW E7XT-X Gas-Shielded Electrodes .....	14	Location of Elements of a Welding Symbol .....	34
Electrodes .....	14		

# Basic Safety Precautions

**Burn Protection.** Molten metal, sparks, slag, and hot work surfaces are produced by welding, cutting, and allied processes. These can cause burns if precautionary measures are not used. Workers should wear protective clothing made of fire-resistant material. Pant cuffs, open pockets, or other places on clothing that can catch and retain molten metal or sparks should not be worn. High-top shoes or leather leggings and fire-resistant gloves should be worn. Pant legs should be worn over the outside of high-top shoes. Helmets or hand shields that provide protection for the face, neck, and ears, and a head covering to protect the head should be used. In addition, appropriate eye protection should be used.

**Electrical Hazards.** Electric shock can kill. However, it can be avoided. Live electrical parts should not be touched. The manufacturer's instructions and recommended safe practices should be read and understood. Faulty installation, improper grounding, and incorrect operation and maintenance of electrical equipment are all sources of danger.

All electrical equipment and the workpiece should be grounded. The workpiece lead is not a ground lead. It is used only to complete the welding circuit. A separate connection is required to ground the workpiece. The workpiece should not be mistaken for a ground connection.


**Fumes and Gases.** Many welding, cutting, and allied processes produce fumes and gases which may be harmful to health. Avoid breathing the air in the fume plume directly above the arc. Do not weld in a confined area without a ventilation system. Use point-of-welding fume removal when welding galvanized steel, zinc, lead, cadmium, chromium, manganese, brass, or bronze. Do not weld on piping or containers that have held hazardous materials unless the containers have been inerted properly.

**Compressed Gas Cylinders.** Keep caps on cylinders when not in use. Make sure that gas cylinders are chained to a wall or other structural support.

**Radiation.** Arc welding may produce ultraviolet, infrared, or light radiation. Always wear protective clothing and eye protection to protect the skin and eyes from radiation. Shield others from light radiation from your welding operation.

AWS also recommends a personal copy of “Arc Welding Safely” and “Fire Safety in Welding and Cutting”.

# Classification System for Carbon Steel Electrodes for SMAW



## Optional Supplemental Designators:

Designates that the electrode meets the requirements of the absorbed moisture test (an optional supplemental test for all low hydrogen electrodes except the E7018M classification, for which the test is required).

Designates that the electrode meets the requirements of the diffusible hydrogen test (an optional supplemental test of the weld metal from low hydrogen electrodes, as-received or conditioned — with an average value not exceeding “Z” mL of H<sub>2</sub> per 100g of deposited metal, where “Z” is 4, 8, or 16).

Designates that the electrode (E7016, E7018, or E7024) meets the requirements for improved toughness — and ductility in the case of E7024.

<b>SMAW Electrodes</b>		
<b>E6010</b>		
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
3/32	50	0.8
	70	1.2
1/8	100	2.1
	130	2.3
5/32	140	2.8
	170	2.9
3/16	160	3.3
	190	3.5
7/32	190	4.5
	230	5.1

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.

<b>SMAW Electrodes</b>		
<b>E6011</b>		
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
3/32	50	0.8
	70	1.2
1/8	110	2.0
	130	2.3
5/32	140	3.5
	175	4.0
3/16	170	4.0
	190	4.2
7/32	175	4.5
	220	5.1

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.

**SMAW Electrodes****E6012**

<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
1/8	100	2.4
	130	2.9
5/32	165	3.2
	200	3.4
3/16	220	4.0
	240	4.2
7/32	275	4.8
	320	5.6
1/4	320	5.6
	380	7.1

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.

**SMAW Electrodes****E6013**

<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
3/32	60	0.9
	75	1.2
1/8	100	1.8
	135	3.0
5/32	140	2.6
	180	3.5
3/16	180	3.2
	220	4.1
7/32	250	5.3
	290	6.1

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.


<b>SMAW Electrodes</b>		
<b>E7018</b>		
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
3/32	70	1.4
	110	1.7
1/8	120	2.6
	160	3.0
5/32	150	3.1
	200	4.3
3/16	200	4.9
	275	5.6
7/32	250	6.5
	340	7.4

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.

<b>SMAW Electrodes</b>		
<b>E7024</b>		
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Dep. Rate<sup>1</sup></b>
1/8	140	4.2
	180	5.1
5/32	180	5.3
	240	7.2
3/16	245	7.5
	290	9.1
7/32	320	9.4
	360	11.6
1/4	400	12.6

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . The efficiency, with a 2" stub loss, is approximately 60%.

# Classification System for Solid and Composite Carbon Steel Electrodes for GMAW



<b>GMAW Electrodes</b>			
<b>ER70S-X Short Arc</b>			
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Volts</b>	<b>Dep. Rate<sup>1</sup></b>
.030	70	15	1.2
	130	21	2.1
.035	80	16	2.1
	190	22	7.3
.045	100	17	2.7
	225	22	8.0

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . Deposition efficiency is assumed to be 94%.


<b>GMAW Electrodes</b>			
<b>ER70S-X Spray Arc</b>			
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Volts</b>	<b>Dep. Rate<sup>1</sup></b>
.030	150	24	4.1
	200	28	6.8
.035	175	24	6.1
	290	28	12.0
.045	200	24	6.7
	315	30	12.5
1/16	275	24	8.7
	500	32	18.0
3/32	350	29	10.0
	600	33	20.0

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . Deposition efficiency is assumed to be 98%.

<b>E70C-XX GMAW Electrodes</b>			
<b>Metal Cored 75% Ar/25% CO<sub>2</sub> Shielded</b>			
<b>Diameter (in.)</b>	<b>Amps</b>	<b>Volts</b>	<b>Dep. Rate<sup>1</sup></b>
.035	150	25	4.4
	250	29	9.4
.045	250	28	8.0
	300	32	11.6
.052	275	29	8.0
	325	30	10.1
1/16	300	30	8.6
	450	34	16.2
5/64	350	27	11.6
	500	29	20.4
3/32	400	31	11.5
	550	32	21.0

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ . Deposition efficiency is assumed to be 92%.

# Classification System for Carbon Steel Electrodes for FCAW



E X X T - X M J H Z

## Optional Supplemental Designators

Designates that the electrode meets the requirements of the diffusible hydrogen test (an optional supplemental test of the weld metal with an average value not exceeding "Z" mL of H<sub>2</sub> per 100g of deposited metal where "Z" is 4, 8, or 16).

Designates that the electrode meets the requirements for improved toughness by meeting a requirement of 20 ft-lb<sub>f</sub> at -40°F (27J at -40°C). Absence of the "J" indicates normal impact requirements.

FCAW Electrodes				
E7XT-X Gas-Shielded				
Diam. (in.)	WFS (ipm)	Volts	Amp (DCEP)	Dep. Rate <sup>1</sup>
.045	200	28	150	4.2
	600	34	320	12.7
.052	150	25	155	4.4
	600	37	430	17.6
1/16	150	27	190	6.1
	500	39	500	20.1
5/64	112	26	250	6.4
	258	31	450	14.8
3/32	124	30	350	9.6
	278	34	550	21.3
7/64	140	30	550	17.1
	190	36	700	23.0
1/8	111	32	600	16.2
	194	38	850	24.2

1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ .

FCAW Electrodes				
Self-Shielded				
Diam. (in.)	WFS (ipm)	Volts	Amp	Dep. Rate <sup>1</sup>
E71T-11 .045			(DCEN)	
	54	15	95	0.9
	140	18	225	2.6
.068	56	17	160	2.1
	132	19	275	5.2
E70T-4 3/32			(DCEP)	
	165	28	354	13.8
	263	30	400	16.1
.120	101	29	450	13.0
	123	33	550	15.5
E70T-7 3/32			(DCEN)	
	135	27	325	8.8
	200	29	400	12.6
7/64	120	29	400	11.5
	175	31	490	15.8


1. Deposition rate in lbs/hr based on 100% arc time. May vary within  $\pm 10\%$ .

## Carbon Arc Gouging Electrodes

<b>Suggested Current Ranges for the Commonly Used CAC-A Electrode Types and Diameters</b>					
<b>Electrode Diameter</b>		<b>DC Electrode with DCEP, A</b>		<b>AC Electrode with AC, A</b>	
<b>in.</b>	<b>mm</b>	<b>min</b>	<b>max</b>	<b>min</b>	<b>max</b>
5/32	4.0	90	150	—	—
3/16	4.8	150	200	150	200
1/4	6.4	200	400	200	300
5/16	7.9	250	450	—	—
3/8	9.5	350	600	300	500
1/2	12.7	600	1000	400	600
5/8	15.9	800	1200	—	—
3/4	19.1	1200	1600	—	—
1	25.4	1800	2200	—	—

# Deposition Rate for Mild Steel for GMAW

## PLOT OF WIRE FEED SPEED AND DEPOSITION RATE







## Recommended Copper Cable Sizes

<b>Cable Sizes for Combined Lengths of Electrode and Work Cables</b>					
<b>Amperes</b>	<b>Percent Duty Cycle</b>	<b>0 to 50 ft.</b>	<b>50 to 100 ft.</b>	<b>100 to 150 ft.</b>	<b>150 to 200 ft.</b>
100	20	8	4	3	2
150	40	6	5	3	2
225	20	4	3	2	1
250	40	2	2	1	1
300	60	1/0	1/0	1/0	2/0
350	60	1/0	1/0	2/0	2/0
400	60	2/0	2/0	2/0	3/0
500	60	2/0	2.0	3/0	3/0

## Guide to Electrode Conditioning and Storage

AWS Electrode Classification	Air Conditioned Storage Before Opening RH = Relative Humidity	Holding Temperature After Opening	Reconditioning Temperature and Time to Affect Weld Quality	
			Recondition Step #1	Rebake Step #2
EXX10, EXX11, EXX12, EXX13	Keep Dry @ Room Temperature 40°–120°F 60% (±10%) RH	100°F (±25°)	Not Required NEVER STORE ABOVE 130° OR BELOW 50% RH	Not Required
EXX20, EXX30 Iron Powder EXX14, EXX24, EXX27	90°F (±20°) 50% Max. RH	150°–200°F	250°–300°F ONE HOUR	350°F (±25°) ONE HOUR
			TWO HOUR TOTAL	
Iron Powder– Low Hydrogen EXX18, EXX28 Low Hydrogen EXX15, EXX16	90°F (±20°) 50% Max. RH	300°F (±50°)	500°–600°F ONE HOUR	700°F (±50°) ONE-HALF HOUR
			ONE & ONE-HALF HOUR TOTAL	
Low Hydrogen– High Tensile EXXX15, EXXX16, EXXX18	90°F (±20°) 50% Max. RH	300°F (±50°)	500°–600°F ONE HOUR	650°F (±50°) ONE-HALF HOUR
			ONE & ONE-HALF HOUR TOTAL	


## Welding Positions — Fillet (plate)



## Welding Positions — Groove (plate)


PLATES HORIZONTAL

1G



PLATES VERTICAL

2G




3G

PLATES VERTICAL




4G

PLATES HORIZONTAL




## Welding Positions — Pipe



PIPE HORIZONTAL, ROTATED.  
WELD FLAT ( $\pm 15^\circ$ ). DEPOSIT  
FILLER METAL AT OR NEAR THE TOP.


**1G ROTATED**

**2G**




PIPE OR TUBE VERTICAL; NOT  
ROTATED DURING WELDING.  
WELD HORIZONTAL ( $\pm 15^\circ$ ).

**2G**




## Welding Positions — Pipe (cont'd)

5G




PIPE OR TUBE HORIZONTAL ( $\pm 15^\circ$ ); NOT ROTATED DURING WELDING. WELD FLAT, VERTICAL, OVERHEAD.

5G



### 6GR; T, K, Y CONNECTION


6G



PIPE INCLINED FIXED ( $45^\circ \pm 5^\circ$ ); NOT ROTATED DURING WELDING.

RESTRICTION RING

TEST WELD



### Thickness and Weight of Steel Plates: 1/32–1 inch

Gauge	Fraction	Decimal	mm	lb/ft <sup>2</sup>
22	1/32	0.031	0.794	1.275
16	1/16	0.063	1.588	2.550
13	3/32	0.094	2.381	3.825
11	1/8	0.125	3.175	5.100
9	5/32	0.156	3.969	6.375
7	3/16	0.188	4.763	7.650
5	7/32	0.219	5.556	8.925
3	1/4	0.250	6.350	10.200
1	9/32	0.281	7.144	11.475
	5/16	0.313	7.937	12.750
	11/32	0.344	8.731	14.025
	3/8	0.375	9.525	15.300
	13/32	0.406	10.319	16.575
	7/16	0.438	11.112	17.850
	15/32	0.469	11.906	19.125
	1/2	0.500	12.700	20.400


Gauge	Fraction	Decimal	mm	lb/ft <sup>2</sup>
	17/32	0.531	13.494	21.675
	9/16	0.563	14.287	22.950
	19/32	0.594	15.081	24.225
	5/8	0.625	15.875	25.500
	21/32	0.656	16.669	26.775
	11/16	0.688	17.463	28.050
	23/32	0.719	18.256	29.325
	3/4	0.750	19.050	30.600
	25/32	0.781	19.844	31.875
	13/16	0.813	20.638	33.150
	27/32	0.844	21.431	34.425
	7/8	0.875	22.225	35.700
	29/32	0.906	23.019	36.975
	15/16	0.938	23.813	38.250
	31/32	0.969	24.606	39.525
	1	1.000	25.400	40.800

## Thickness and Weight of Steel Plates: 1-2 inch

Fraction	Decimal	mm	lb/ft <sup>2</sup>
1-1/32	1.031	26.194	42.075
1-1/16	1.063	26.988	43.350
1-3/32	1.094	27.781	44.625
1-1/8	1.125	28.575	45.900
1-5/32	1.156	29.369	47.175
1-3/16	1.188	30.163	48.450
1-7/32	1.219	30.956	49.725
1-1/4	1.250	31.750	51.000
1-9/32	1.281	32.544	52.275
1-5/16	1.313	33.338	53.550
1-11/32	1.344	34.131	54.825
1-3/8	1.375	34.925	56.100
1-13/32	1.406	35.719	57.375
1-7/16	1.438	36.513	58.650
1-15/32	1.469	37.306	59.925
1-1/2	1.500	38.100	61.200


Fraction	Decimal	mm	lb/ft <sup>2</sup>
1-17/32	1.531	38.894	62.475
1-9/16	1.563	39.688	63.750
1-19/32	1.594	40.481	65.025
1-5/8	1.625	41.275	66.300
1-21/32	1.656	42.069	67.575
1-11/16	1.688	42.863	68.850
1-23/32	1.719	43.656	70.125
1-3/4	1.750	44.450	71.400
1-25/32	1.781	45.244	72.675
1-13/16	1.813	46.038	73.950
1-27/32	1.844	46.831	75.225
1-7/8	1.875	47.625	76.500
1-29/32	1.906	48.419	77.775
1-15/16	1.938	49.213	79.050
1-31/32	1.969	50.006	80.325
2	2.000	50.800	81.600

## How to Use Weld Fillet Gage




**PLACEMENT**

BE CERTAIN BLADE  
EDGE IS SQUARE  
WITH WELDED PARTS.



**CONVEX WELDS**

FOR CONVEX WELDS: USE BLADE WITH SINGLE ARC AT  
APPROPRIATE SIZE. FOR CONCAVE WELDS: USE BLADE  
WITH DOUBLE ARC AT APPROPRIATE SIZE.



**CONCAVE WELDS**


## Commercial Pipe Sizes and Wall Thicknesses (ASA-B36.10 and B36.19)

Nominal Pipe Size	Outside Diam.	Nominal Wall Thicknesses in inches for								
		Sched. 5s <sup>1</sup>	Sched. 10s <sup>1</sup>	Standard <sup>2</sup>	Sched. 40	XS <sup>3</sup>	Sched. 80	Sched. 120	Sched. 160	XX Strong
1/8	0.405	—	0.049	<i>0.068</i>	0.068	<i>0.095</i>	0.095	—	—	—
1/4	0.540	—	0.065	<i>0.088</i>	0.088	<i>0.119</i>	0.119	—	—	—
3/8	0.675	—	0.065	<i>0.091</i>	0.091	<i>0.126</i>	0.126	—	—	—
1/2	0.840	0.065	0.083	<i>0.109</i>	0.109	<i>0.147</i>	0.147	—	0.188	0.294
3/4	1.050	0.065	0.083	<i>0.113</i>	0.113	<i>0.154</i>	0.154	—	0.219	0.306
1	1.315	0.065	0.109	<i>0.133</i>	0.133	<i>0.179</i>	0.179	—	0.250	0.358
1-1/4	1.660	0.065	0.109	<i>0.140</i>	0.140	<i>0.191</i>	0.191	—	0.250	0.382
1-1/2	1.900	0.065	0.109	<i>0.145</i>	0.145	<i>0.200</i>	0.200	—	0.281	0.400
2	2.375	0.065	0.109	<i>0.154</i>	0.154	<i>0.218</i>	0.218	—	0.344	0.436
2-1/2	2.875	0.083	0.120	<i>0.203</i>	0.203	<i>0.276</i>	0.276	—	0.375	0.552
3	3.5	0.083	0.120	<i>0.216</i>	0.216	<i>0.300</i>	0.300	—	0.438	0.600
3-1/2	4.0	0.083	0.120	<i>0.226</i>	0.226	<i>0.318</i>	0.318	—	—	—
4	4.5	0.083	0.120	<i>0.237</i>	0.237	<i>0.337</i>	0.337	0.438	0.531	0.674
5	5.563	0.109	0.134	<i>0.258</i>	0.258	<i>0.375</i>	0.375	0.500	0.625	0.750
6	6.625	0.109	0.134	<i>0.280</i>	0.280	<i>0.432</i>	0.432	0.562	0.719	0.864


### NOTES:

1. Schedules 5s and 10s are available in corrosion resistant materials and Schedule 10s is also available in carbon steel in sizes 12 in. and smaller.
2. Thicknesses shown in *italics* are also available in stainless steel, under the designation Schedule 40s.
3. Thicknesses shown in *italics* are also available in stainless steel, under the designation Schedule 80s.

## Material Identification

Test	Low Carbon Steel	Med. Carbon Steel	High Carbon Steel	High Sulphur Steel
 <i>Appearance Test</i>	Dark Grey	Dark Grey	Dark Grey	Dark Grey
 <i>Magnetic Test</i>	Strongly Magnetic	Strongly Magnetic	Strongly Magnetic	Strongly Magnetic
 <i>Chisel Test</i>	Continuous Chip Smooth Edges Chips Easily	Continuous Chip Smooth Edges Chips Easily	Hard to Chip Can Be Continuous	Continuous Chip Smooth Edges Chips Easily
 <i>Fracture Test</i>	Bright Grey	Very Light Grey	Very Light Grey	Bright Grey Fine Grain
 <i>Flame Test</i>	Melts Fast Becomes Bright Red Before Melting	Melts Fast Becomes Bright Red Before Melting	Melts Fast Becomes Bright Red Before Melting	Melts Fast Becomes Bright Red Before Melting
 <i>Spark Test*</i>  *For best results, use at least 5,000 surface feet per minute on grinding equipment. $\left( \frac{\text{Cir.} \times \text{R.P.M.}}{12} \right) = \text{S.F. per Min.}$	  Long Yellow Carrier Lines (Approx. 20% Carbon or Below)	  Yellow Lines Sprigs Very Plain Now (Approx. 20% to 45% Carbon)	  Yellow Lines Bright Burst Very Clear Numerous Star Burst (Approx. 45% Carbon and Above)	  Swelling Carrier Lines Cigar Shape

## Material Identification (cont'd)

Test	Manganese Steel	Stainless Steel	Cast Iron	Wrought Iron
 <b>Appearance Test</b>	Dull Cast Surface	Bright, Silvery Smooth	Dull Grey Evidence of Sand Mold	Light Grey Smooth
 <b>Magnetic Test</b>	Non Magnetic	Depends on Exact Analysis	Strongly Magnetic	Strongly Magnetic
 <b>Chisel Test</b>	Extremely Hard to Chisel	Continuous Chip Smooth Bright Color	Small Chips About 1/8 in., Not Easy to Chip, Brittle	Continuous Chip Smooth Edges, Soft & Easily Cut & Chipped
 <b>Fracture Test</b>	Coarse Grained	Depends on Type Bright	Brittle	Bright Grey Fibrous Appearance
 <b>Flame Test</b>	Melts Fast Becomes Bright Red Before Melting	Melts Fast Becomes Bright Red Before Melting	Melts Slowly Becomes Dull Red Before Melting	Melts Fast Becomes Bright Red Before Melting
 <b>Spark Test*</b>  *For best results, use at least 5,000 surface feet per minute on grinding equipment. $\left( \frac{\text{Cir.} \times \text{R.P.M.}}{12} \right) = \text{S.F. per Min.}$	  Bright White Fan-Shaped Burst	  1. Nickel-Black Shape Close to Wheel. 2. Moly-Short Arrow Shape Tongue (only). 3. Vanadium-Long Spear- point Tongue (only)	  Red Carrier Lines (Very Little Carbon Exists)	  Long, Straw Color Lines (Practically Free of Bursts or Sprigs)

## Guide for Manual Oxyfuel Gas Cutting Using Natural Gas

Plate Thickness (in.)	Diameter of Cutting Orifice <sup>1</sup> (in.)	Nominal Oxygen Pressure (psi)	Minimum Natural Gas Pressure (psi)	Cutting Speed <sup>2</sup> (in./min)
1/8	0.046	30-40	3-6	20-28
1/4	0.046	30-40	3-6	18-28
3/8	0.046	30-40	3-6	16-20
1/2	0.059	30-40	3-6	13-17
3/4	0.059	30-40	3-6	10-15
1	0.059	30-40	3-6	9-13
1-1/2	0.067	40-50	3-6	7-12
2	0.067	40-50	3-6	6-10
2-1/2	0.067	40-50	3-6	6-9
3	0.093	40-55	3-9	5-8
4	0.093	40-55	3-9	5-7
5	0.093	50-60	3-10	4-6
6	0.110	50-60	3-10	4-6
7	0.110	50-70	3-12	3-5
8	0.110	50-70	3-12	3-4
10	0.110	50-70	3-12	3-4
12	0.110	50-70	3-12	2-3

1. Use two-piece tips.

2. Variations in cutting speeds may be caused by mill scale on plate, variation in oxygen purity, flame adjustment, condition of equipment, impurities in steel, and variation in heat content of natural gas.

3. Tip, drill or orifice diameter size will vary with each tip according to manufacturer's specification.

## Guide for Manual Oxyfuel Gas Cutting Using Acetylene

Material Thickness (in.)	Drill Size	Cutting Orifice Diameter (in.) (center hole)	Approximate Pressure of Gas (psi)		Manual Travel Speed (in./min.)
			Acetylene	Oxygen	
1/8	60	0.040	3	10	20-22
1/4	60	0.040	3	15	16-18
3/8	55	0.052	3	20	14-16
1/2	55	0.052	3	25	12-14
3/4	55	0.052	4	30	10-12
1	53	0.060	4	35	8-11
1-1/2	53	0.060	4	40	6-7
2	49	0.073	4	45	5-7
3	49	0.073	5	50	5-6
4	49	0.073	5	55	4-5
5	45	0.082	5	60	3-4
6	45	0.082	6	70	3-4
8	45	0.082	6	75	3

1. Tip, drill or orifice diameter size will vary with each tip according to manufacturer's specification.

## Guide for Manual Oxyfuel Gas Cutting Using Propylene

Plate Thickness (in.)	Tip Size	Fuel Gas Pressure (psi)	Cutting Oxygen Pressure (psi)	Cutting Speed (ipm)
1/8	0000	3-7	30-50	24-34
3/16	000	3-7	30-50	24-34
1/4	00	5-10	30-50	22-32
3/8	0	5-10	30-50	20-30
1/2	0	5-10	30-50	18-28
3/4	1	5-10	40-50	16-22
1	1	5-10	40-50	14-20
2	2	5-10	40-50	10-15
2-1/2	3	5-10	50-60	9-14
3	3	5-10	50-60	8-13
4	4	5-10	50-60	7-12
6	5	5-10	70-80	5-9
8	6	10-15	60-70	4-8
10	7	10-15	60-70	4-6
12	8	10-15	40-70	3-5
14	9	10-15	50-85	2-4
15	10	10-15	50-90	2-3
16	11	10-15	50-90	1-2-1/2
18	12	10-15	50-90	1-2

1. Tip, drill or orifice diameter size will vary with each tip according to manufacturer's specification.


## Basic Welding Symbols and Their Location Significance

Location Significance	Fillet	Plug or Slot	Spot or Projection	Stud	Seam	Back or Backing	Surfacing	Flange Corner	Flange Edge
Arrow Side									
Other Side				Not Used			Not Used		
Both Sides		Not Used	Not Used	Not Used	Not Used	Not Used	Not Used	Not Used	Not Used
No Arrow Side or Other Side Significance	Not Used	Not Used		Not Used		Not Used	Not Used	Not Used	Not Used

## Basic Welding Symbols and Their Location Significance (cont'd)

Location Significance	Groove							Scarf for Brazed Joint
	Square	V	Bevel	U	J	Flare-V	Flare-Bevel	
Arrow Side								
Other Side								
Both Sides								
No Arrow Side or Other Side Significance		Not Used	Not Used					

## Location of Elements of a Welding Symbol



## Other Publications Also Available from AWS

Title	Order Number
Welding Processes: Welding Handbook, Vol. 2, 8th edition	WHB-2.8
Recommended Practices for Gas Metal Arc Welding	C5.6-94R
Recommended Practices for Welding Austenitic Chromium-Nickel Stainless Steel Piping and Tubing	D10.4-92R
Recommended Practices and Procedures for Welding Low Carbon Steel Pipe	D10.12-89
Guide for Visual Inspection of Welds	B1.11-88
Welding Inspector's Tool Kit	TK
Standard for AWS Certified Welders (FREE)	QC7
Specifications for Qualification and Certification of Welding Inspectors (FREE)	QC1



# **American Welding Society**

---

550 N. W. LeJeune Road, Miami, Florida 33126